

Temp. & RH% Datalogger

Temp. + RH% datalogger (Interface: Cable)



- ▲ RECORDING TEMP. & HUMIDITY FOR QUALITY CONTROL
- ▲ SEVERAL METHODS TO START RECORDING:
 - 1) 88395: BUTTON/SCHEDULE /IMMEDIATELY/REPEAT/ ON LINE START
 - 2) 88398: MAGNET/SCHEDULE/IMMEDIATELY/REPEAT/ ON LINE START
- ▲ WATER RESISTANT IP54 RATING HOUSING
- ▲ 2 WAYS TO PROGRAM & DOWN LOAD :
 - 1) VIA PC: RS232 OR USB CABLES
 - 2) VIA LOGGER PRINTER 9801: THIS IS A 3 FUNCTION IN 1 PRINTER FOR PROGRAMING & DOWNLOAD
- ▲ YELLOW RECORDING LED INDICATOR
- ▲ RED LED FLASH WHILE EXCEEDING THRESHOLD
- ▲ CAN BE USED AS REGULAR TEMP. & RH% MONITOR WHILE SETTING AS NON-SLEEP AFTER RECORDING
- ▲ UP TO 15999 POINTS MEMORIES
- ▲ POWERED BY LITHIUM BATTERY WITH LONG LIFE TIME
- ▲ LOW BATTERY INDICATOR

Optional



EXTERNAL TEMP. PROBE
 P/N: VZ87P6AZ
 FOR 88395/398
 COLOR: BLACK
 SIZE: 15CM PROBE W/HANDLE
 CABLE: 116CM W/2.5MM JACK



RS232 CABLE
 P/N: VZ88193NLP
 SIZE : cable 125cm
 -D-sub 9pin connector to PC
 -2.5mm dia. Stereo phone jack to logger



USB CABLE
 P/N: VZUSBZD
 USB 2.0 INTERFACE
 SIZE : cable 125cm
 -USB connector to PC
 -2.5mm dia. stereo phone jack to logger



3 IN 1 DATALOGGER PRINTER
 P/N: VZ9801AZ
 USB connector to PC
 Connect with 88395/88398 via VW302A00 cable



LOGGER TO PRINTER CABLE
 P/N: VW302A00
 SIZE : cable 120 cm
 -2.5mm dia. stereo phone jack to logger.
 -3.5mm dia. stereo phone jack to printer.
 This is cable is a standard accessory while purchasing 9801 printer.

Model	88395	88398
Air temp. range	-40~85°C	
Air temp. resolution	0.1°C/°F	
Air temp. accuracy	+/-0.6°C (-20~50°C), others +/-1.2°C	
Humidity. range	0%RH~100%RH	
Humidity resolution	0.1%RH	
Humidity accuracy	+/-3%RH (at 25°C, 10~90%RH, others +/-5%RH)	
External temp. range	-40~100°C	
External temp. Accuracy	+/-0.6°C (-20~50°C), others +/-1.2°C	
Sampling points	15999	
Button to on/off	YES	N/A
Battery life time	>5 MONTHS	
LCD size (mm)	13(H)x33(W)	
Operating temp.	0~50°C	
Operating RH%	Humidity < 80%	
Storage temp.	-20~50°C	
Storage RH%	Humidity < 90%	
Dimension(mm)	75.5x53x23.5	
Weight	~100g	
Battery	CR2 x 1pc	
Standard Package	Meter/Battery/Manual/Paper box	
Optional Accessory	External probe / Software kit /9801 printer	